

GROUP 4A

TRANSMISSION SHIFT LINKAGE

ADJUSTMENTS

SECTIONS IN GROUP 4A

Section	Subject	Page
4A-A	Super Turbine 300 Transmission Shift Linkage Adjustment	4-1
4A-B	3-Speed Synchromesh Transmission Shift Linkage Adjustment	4-3
4A-C	4-Speed Synchromesh Transmission Shift Linkage Adjustment	4-7

4A-A SUPER TURBINE 300 TRANSMISSION SHIFT LINKAGE ADJUSTMENT




Fig. 4A-1




Fig. 4A-2




Fig. 4A-3

4A-B 3-SPEED SYNCHROMESH TRANSMISSION LINKAGE ADJUSTMENT




Fig. 4A-4




Fig. 4A-5




Fig. 4A-6




Fig. 4A-7




Fig. 4A-8




Fig. 4A-9




Fig. 4A-10

4A-C 4-SPEED SYNCHROMESH LINKAGE ADJUSTMENT




Fig. 4A-11




Fig. 4A-12




Fig. 4A-13