

OE specifications for 401 and 425 camshafts. Remember, these are measured at .002", NOT .005" or .050"!

CAM PART NO.	1185918	1351515	1359442	1358100	1362242	1368091	1368090
NO. ON SHANK	1174480	1174480	1374480	1674480	1362241	1362241	1362241
401	1959-61	1962-63	Late 1963-64				
425				1963	Late 1963-64	1965	1966
425 2X4					1964	1965-66	
MACHINED GROOVE IN SHANK	.060"	NONE	NONE	.060"	.060"	.120"	NONE
TIMING ADVANCE OF #1 EXHAUST LOBE AHEAD OF SPROCKET KEYWAY	2°30'	5°	5°	0°30'	0°30'	0°30'	5°
EXHAUST DURATION .002"	299°	302°	295°	299°	299°	299°	295°
EXHAUST LIFT	.441	.439	.431	.441	.441	.441	.431
INTAKE DURATION .002"	290°	295°	295°	290°	290°	290°	295°
INTAKE LIFT	.439	.439	.431	.439	.439	.439	.431
SPACING	109°	114°	114°	109°	109°	109°	114°
EXHAUST OPEN BBC	75°	76°	76°	71°	71°	71°	76°
EXHAUST CLOSE ATC	44°	46°	39°	48°	48°	48°	39°
INTAKE OPEN BTC	33°	28°	28°	29°	29°	29°	28°
INTAKE CLOSE ABC	77°	87°	87°	81°	81°	81°	87°
OVERLAP	77°	74°	67°	77°	77°	77°	

TeamBuick.com